

PROGRAMMING CERTIFICATE

406MHZ BEACON

BEACON

Serial Number : 200-30237

Brand : **McMurdo Ltd.**

Model : **G5**

Battery Expiry Date : **MAY 2019**

OWNER

Name :

Address : _____

Country : _____

Post / Zip Code : _____

Home Phone : _____

Work Phone : _____

Mobile Phone : _____

PROGRAMMING

Flag : **265 - Sweden**

Coding : **MMSI - 265506330**

Protocol : **MMSI STD. LOC.**

Unique ID : **2124F73B40FFBFF**

Programmed Message : **FF FE 2F 90 92 7B 9D A0 7F**
DF FD FD A6 37 83 E0 F6 6C

DEALER STAMP



Dealer's Signature :

P. Bengtsson

Date :

2014-05-22

406 MHZ BEACON WARRANTY FORM

BEACON Unique ID <u>2124F73B40FFBFF</u> Serial Number <u>200-30237</u> Brand <u>McMurdo Ltd.</u> Model <u>G5</u> Country <u>Sweden</u> Programmed # <u>MMSI - 265506330</u> Protocol <u>MMSI STD. LOC.</u>	PLEASE RETURN THIS FORM TO THE ADDRESS BELOW * McMurdo Ltd. Silver Point Airport Service Road Portsmouth PO3 5PB UK ☎ +44(0)23 9262 3900 FAX +44(0)23 9262 3998
OWNER Name _____ Address _____ _____ _____ Country _____ Post / ZIP Code _____ Home Phone _____ Work Phone _____ Mobile Phone _____	DEALER PURCHASE DATE : (Day / Month / Year)
DETAILS <input checked="" type="checkbox"/> <input type="checkbox"/> Change Of Owner <input type="checkbox"/> Change Of Address <input type="checkbox"/> Other : _____ <input type="checkbox"/> Refurbished Unit <input type="checkbox"/> Re-Programmed	

DEALER INSTRUCTIONS

Please complete the DEALER and DETAILS sections before passing to the beacon owner.

BEACON OWNER INSTRUCTIONS

Please complete your personal details above and mail or fax the completed form to the address shown at the top. Complete the DETAILS section where appropriate.

***UNREGISTERED WARRANTY CLAIMS MAY BE REJECTED.**

mcmurdo

First EPIRB Shore Based Maintenance Sheet


EPIRB Serial Number:

200-30237

The above S/N EPIRB, during its manufacture has been tested to the required parameters as noted in IMO MSC/Circ 1039.

Operator Signature/Stamp:

Date: 8.4.14



The person installing the EPIRB should indicate below the next recommended SBM maintenance date (refer to note 1 below).

Date of Installation	
Year	2014
Month	MAY

Date of Next SBM	
Year	
Month	

Installer Signature/Stamp:

Date: 2014-05-23

Important notes:

1. The next shore-based maintenance must be performed at the interval specified by the Flag State Administration, which must not exceed five years from the date the EPIRB is first installed on the vessel.
2. Shore-Based Maintenance is equivalent to Annual Maintenance in the year it is performed (IMO MSC/Circ.1040).
3. IMO MSC/Circ 1039 recommends that SBM be performed when the battery is changed. The EPIRB battery expiry date label is not an indication of the first applicable SBM date.
4. A copy of this SBM sheet should be retained on board the vessel.

For further information please contact:

Orolia Ltd.

Tel: +44 (0) 23 9262 3900, Fax: +44 (0) 23 9262 3998,

Email: service.mcmurdo@orolia.com Web: www.mcmurdomarine.com

Silver Point, Airport Service Road, Portsmouth, P03 5PB, United Kingdom

(82-997N Issue 4)